

May 2014

New firmware release version 1.58 for the Mamiya 645DF Camera body.

Firmware version in the 645DF camera body can be checked on the LCD screen of the camera by selecting custom function 99.

Updating to version 1.58 (or newer) requires Firmware Updater 3.3, available from:
<http://www.mamiyaleaf.com/firmware.html>

Firmware version 1.58 is a major stability update, and addresses numerous scenarios of “Err DB”, “Cap DB” and “No DB”

Firmware version 1.58 is highly recommended for all 645DF cameras. This firmware corrects or improves a number of issues with digital back communication, settings, timing and general stability. For best performance with a Leaf Credo back it is recommended to use the latest Credo firmware, also available from
<http://www.mamiyaleaf.com/firmware.html>

You can update your firmware in the Mamiya 645DF camera by using the USB port on your V – Grip^{Air} – If you do not have access to a V-Grip^{Air}, please contact your local Mamiya Leaf dealer, in order to get your camera body upgraded to the latest version.

For more information about how to upgrade the camera body using the V-Grip^{Air}, please refer to the following Knowledge Base article
<http://www.phaseone.com/en/search/article.aspx?articleid=1914&languageid=1>